Functions	Series 575
ORIGIN (ABS-Zero)	(a)
Digimatic data output	(a)
ON/OFF	(a)
Counting direction switchable	<u> </u>

Specifications

Specifications			
Accuracy	Refer to the list of specifications (excluding quantizing error)		
Scale	Capacitance type, ABSOLUTE linear encoder		
Stem Ø	8 mm (ISO/JIS type)		
Max. response speed	Unlimited		
Contact point	Carbide ball, thread M 2.5 x 0.45 mm (ISO/JIS type)		
Alarm	Low voltage, counting value composition error		
Power supply	1 battery SR-44		
Battery life	approx. 20.000 hours		
Digital step	0,01 mm		
Display	LCD, character height 8.5 mm		

Standard accessories

No.	Description
137693	Lifting handle


Optional accessories

No.	Description	
540774	Spindle lifting cable	
Digimatic Signal Cables		
905338	Digimatic cable (1 m)	
905409	Digimatic cable (2 m)	
02AZD790F	Connecting cable U-Wave	
06ADV380F	USB Input Tool Direct cable (2 m)	

540774:moving measuring range max. 12mm
For USB Input Tool Direct cable:
a footswitch (no. 937179T), a USB- footswitch adapter (no. 06ADV384)
and USB-ITPAK Software (no. 06ADV386) are required.

Consumable spares

No.	Description
938882	Battery SR44
901312	Standard contact point



ABSOLUTE Digimatic Indicator ID-U


Series 575

This is a slim type of digital indicator with a 25mm range.

The ABSOLUTE Digimatic Indicator ID-U offers you the following benefits:

- The ABSOLUTE sensor means you don't have to carry out origin setting every time you power it on, saving you time and hassle.
- Its compact design makes it ideal for installing into measuring fixtures.
- Exceptional battery life.





Metric

No.	Range [mm]	Accuracy	Measuring force [N]	Mass [g]
575-121	25.4	0,02 mm	≤ 1,8	140



