

Rocket 620AP RAID Firmware Updated Guide

Download the **RAID** Firmware from product webpage:

http://www.highpoint-tech.com/USA_new/series_r600-download.htm

Extract and prepare the firmware package.

Boot to true DOS environment and run the “**go.bat**” under the firmware folder to start firmware update. Follow the on screen instruction to complete the firmware update:

1. Run Go.bat

```
C:\I\9130\CPU\HCCI>go.bat
Can not set environment variable 'TOPDIR'.
Environment full?

MVF_MAG v1.0.0.2470

-----
MARVELL FLASH TOOL
-----

MVF_MAG v1.0.0.2470
----- Adapter 0 Info -----
DevId:      9130 DevFunc:    00 Bus:        01
ClassCode:  0106 RevId:     11 Ver:         00
FlashCount   01 SubVer:     00
-----

image.bin >> /dev_9130/00000000..
Press "Y" to start, other to skip..
```

2. Press “Y” to start flash update.

3. Reboot system after the flash is finished.

```
ClassCode:   0106 RevId:      11 Ver:         00
FlashCount   01 SubVer:      00

-----
image.bin >> /dev_9130/00000000..
Press "Y" to start, other to skip..
Erasing...
Bravo!! Erase Successful!!
Data is flashed perfectly!!

AUTOLoad flashed successful!!
```