

Bartleson Ranch (weekend 2)

02/05/22
same as
before

- 112 electrodes
- 5 m spacing

• Schlumberger invenise.

• CMD file:

• Data file:


• Conditions: 46.5°F, windy, green grass

• Grassy field,

• Synchronizing: (35° 5' 37", -120° 32' 50" W)

• Elevation Survey:

• Strike (E1 → 112): 33°



* Note: E112 site is located near (< 20m) from power lines + Highway 1

* holes were dug @ electrodes, tin foil placed, salt water poured, then covered with dirt.

2/05/22

Elevation Survey

Location: Grass Field on NE side of the property

Electrode #, level

1.68m

Units: meters

1) 1.68

2) 1.62

3) 1.44

4) 1.48

5) 1.60

6) 1.56

7) 1.62

8) 1.62

9) 1.58

10) 1.52

11) 1.60

12) 1.52

13) 1.56

14) 1.58

15) 1.16

16) 1.1

17) 1.08

18) 1.08

19) 1.18

20) 1.1

21) 1.16

22) 1.20

23) 1.32

24) 1.24

25) 1.16

26) 1.15

27) 1.14

28) 1.18

29) 1.12

30) 1.26

31) 1.36

32) 1.26

33) 1.26

34) 1.38

35) 1.32

36) 1.22

37) 1.12

38) 1.16

39) 1.18

40) 1.14

41) 1.28

42) 1.2

43) 1.2

44) 1.14

45) 1.18

46) 1.6

47) 1.22

48) 1.22

49) 1.28

50) 1.22

51) 1.24

52) 1.26

53) 1.24

54) 1.28

55) 1.26

56) 1.34

57) 1.32

58) 1.30

59) 1.38

60) 1.38

61) 1.28

62) 1.26

63) 1.32

64) 1.28

65) 1.28

66) 1.26

67) 1.54

68) 1.28

69) 1.12

70) 1.02

71) 0.98

72) 0.96

73) 0.94

74) 1.02

75) 1.03

76) 1.04

77) 1.04

78) 1.24

79) 1.12

80) 1.06

81) 0.98

82) 1.04

83) 1.1

84) 1.08

85) 1.16

86) 1.14

87) 1.18

88) 1.18

89) 1.20

90) 1.10

91) 1.12

92) 1.06

93) 1.02

94) 1.32

95) 1.34

96) 1.52

97) 1.58

98) 1.58

99) 1.82

100) 1.74

101) 1.66

102) 1.66

103) 1.60

104) 1.72

105) 1.84

106) 1.96

107) 1.68

108) 1.76

109) 1.58

110) 1.76

111) 1.72

112) 1.86